


3615



Customer services:



01942 524 100



cseurope@dorel.com



Dorel Home Furnishings Ltd.
Building 4, Imperial Place, Maxwell Road,
Borehamwood WD6 1JN United Kingdom.

REFERENCE NO:

Please retain this booklet as you will be asked
to quote this number for any warranty or
product related queries


3615

Thank you for purchasing this desk. Please read the instructions carefully before use to ensure safe and satisfactory operation of this product.

Pre-assembly preparation

Please ensure instructions are read in full before attempting to assemble this product

Necessary Tools



Note: Some of the tools shown here are optional and are required only for quick assembly of this product

Please check the pack contents before attempting to assemble this product. A full checklist of components is given in this leaflet. If any components are missing, please contact the retailer from whom you bought this product.


This product is **HEAVY**, it should be assembled as near as possible to the point of use. **TAKE CARE WHEN LIFTING** to avoid personal injury and (or) damage to the product.








This product takes approximately **30 MINUTES** to assemble with **2 PEOPLE**.




The fittings pack contains **SMALL ITEMS** which should be **KEPT AWAY FROM YOUNG CHILDREN**.

Read this leaflet in full before commencing assembly.




■PARTS LIST



 1 X2	 2 X2	 3 X1	
 4 X4	 5 X2	 6 X2	 7 X1
 8 X1	 9 X2	 10 X2	 11 X1

12  X1	13  X1		
14  X1	15  X1	16  X1	
17  X1	18  X1	19  X1	20  X1
21  X6			

SCREWS LIST

PART	QTY.	ITEM		PART	QTY.	ITEM	
A	14	6X25 MM		F	4	4X35 MM	
B	20	6X15 MM		G	14	Φ 12 MM	
C	8	6X40 MM			1	M 4	
D	2	4X20 MM			1		
E	18	5X40 MM					


6X25MM BOLT INSTALLATION AS BELOW:



Bolt



Connecting piece



Pin




Panel




No gap


A1.




A2.




A3.




A4.






Rotate connecting piece if found in position illustrated above





Correct orientation to receive bolts

■ ASSEMBLY STEPS:



4



SCREWS


A 6X25 MM

x4

G Φ 12 MM

x4

5




SCREWS

E 5X40 MM

x4

6




SCREWS

A 6X25 MM


x6

G Φ 12 MM

x6



7




SCREWS

E 5X40 MM

x2



8




SCREWS

E 5X40 MM

x12



9





SCREWS

C 6X40 MM

x4



10



SCREWS


A 6X25 MM

x4


G Φ 12 MM

x4

11



12




SCREWS


F 4X35 MM

x4

13



14






■ SCREWS

D 4X20 MM

 **x2**



15



16

