




A		6x30	x8
B		8x30	x26
C		7x34	x29
D		15x12	x29
E		3,5x15	x20
F		H30/L400	x4
G		5x38	x8


H		7x50	x2
J		7x70	x3
K		D38	x4
L		D4x13	x2
M		D20	x3
N		4mm	x1

1




A		6x30	x8
B		8x30	x16

2




C		7x34	x14
---	---	------	-----

3



D		15x12	x4
K		D38	x2


4




D		15x12	x4
K		D38	x2

5

1.





2.




U		H30/L400	x4
---	---	----------	----


6



1.







2.



F		H30/L400	x2
E		3,5x15	x6

7




F		H30/L400	x2
E		3,5x15	x6

8





4mm



H		7x50	x2
L		D4x13	x2

9






C



7x34

x2

10




D



15x12


x8

11




C		7x34	x13
---	---	------	-----

12





B		8x30	x10
---	---	------	-----

13



D		15x12	x9
J		7x70	x3

14




D




15x12

x4


15



16



x2



G





5x38

x8

17

x2




E



3,5x15

x8


F



H30/L400

x4

18



M



D20

x3